SEAWALL INSPECTION ASSESSMENT

SOURCE: TetraTech Report: November 2024

SEAWALL PHASES

- PHASE 1. *Completed 2015.*
- PHASE 2. *Completed 2021.*
- PHASE 3. *Awaiting CCC requirement completion.*
- PHASE 4.
- PHASE 5.
- PHASE 6.
- EMERGENCY TIE BACK INSTALLATION
  (2027?) 11 - 31 Vista del Golfo

SEVERE DEFECTS

Properties receiving a score of "3" (severe defect) in the Inspection Results Matrix.

- SEVERE DEFECT: PANEL, GROUT, SIDEWALK, PILE CAP.
- SEVERE DEFECT: PANEL & GROUT / SOIL LOSS
  Grouting ratings are based on probe depth measurement and estimated subsidence. Inspection Report pg. 15.
- SEVERE DEFECT: GROUT / SOIL LOSS (only)
  Grouting ratings are based on probe depth measurement and estimated subsidence. Inspection Report pg. 15.
- SEVERE DEFECT: GROUT / SOIL LOSS @ STREET END
  Grouting ratings are based on probe depth measurement and estimated subsidence. Inspection Report pg. 15.

